

Jounce Bumper Brkt Welds:

OK

Ball Stud:

Seated

Push out B/P Spec 2000 # Min.

Push out 3800 # and still seated

Lower Control Arm Stamping:

OK

Date: SKD 2345

Summary: The L.H. lower control arm stampings from SKD appear to have a small radius at the transition of the side wall to the ball stud nose. SKD has changed the trim to increase the radius to one inch and provide additional strength in the ball stud area.

D. H. Pokriefka

D. H. Pokriefka
Chief Inspector

cc: R.M. Brown

0000201

G-30 4/4/A HISTORY
(P/N 14026585 4/4/A ASM AS SERVICED)

07AUG7 8:25 EARL GANTSCH - FLEET SERVICE CAP 8-562-5533

- G-30 CUTAWAYS - (18 ASBS) SCHOOL BUSES, 6.2 L ASESLS
- * • 13 4/4/A ASM CRACKED IN BALL JOINT AREA (24) ONLY
(P/N 14026585 SERVICED ASM)
- * • 45 BUSES IN FLEET (TYPICAL VIN # 2904G31J199101766)
- OCCURRENCES AT APPROX 50,000 + MILES
- BUSES MADE BY CARPENTER (BODY WORKS)
- (SAN DIEGO CITY SCHOOLS
MAINTENANCE DEPT
2351 CARDINAL LANE
SAN DIEGO, CALIF 92123
ATTN: DAN HARGREAVES (MAINT. MGR.) (619) 278-7440)
- PHOTOS PROVIDED (POOR)
- STATE HIGHWAY PATROL AND D.O.T. INVOLVED

07AUG7 7:26 DAN HARGREAVES - (MAINT. MGR.,

- FRT JUMP TAKES ON 2 VEHICLES VEHICLED AS:
SAP 15597838

- * • 9 4/4/A ASM CRACKED CHANGED 7 (DIFFERS FROM E. GANTSCH)
- HELWIG TRANSVERSE LEAF SPRINGS ADDED (BY HIMSELF)
DUG TO 2 TIRES WEARING OUT AT 8000 MILES (RIPING TIRES)
- 10000 MILES WEARING OUT AT 3-4000 MILES
- * • 33 BUSES IN FLEET (DIFFERS FROM E. GANTSCH)
- TOLD BY THOMAS BUS COMPANY (COMPETITOR TO CARPENTER) THAT
THE CHASSIS USED IS ONLY 8600 GVW.
- CARPENTER MAINTAINS THAT VEHICLE IS RATED AT 10,000 GVW.

10AUG7 8:05 GENE STURM - TVB CHASSIS DESIGN ENGR- 3-292-3108

- MUST SEND IDENTICAL REPLACEMENT 4/4/A ASM. (NOT TIRES
REINFORCED FOR F-12 HEAVY DUTY OPTION)
- NO EVIDENCE TO SUPPORT A NEED FOR HEAVY DUTY AXLES
OR CROSS MEMBER. PARTS MADE TO MEET ALL
SCHEDULE REQUIREMENTS.
- THIS PROBLEM IS DUE TO IMPROPER TRANSITION RADII AT THE
BALL JOINT (REF. T.R. # T-879-03A-002LT)

000202

16 AUG 87 11:30 EARL GAUTSCHI

- SHIP (13) PC LH 14026585
- (3) ~~SH~~ PC RH 14026586 (FILES RAISED 12 AUG 87)
- WILL BE ORDERED THRU WAREHOUSING WITH A P.O.
 (AGREED TO DO THIS PER SD REQUEST, ORIGINAL
 DIRECTION FROM ME 97 AUG 87)

12 AUG 87 8:11 EARL GAUTSCHI

- KNOWN AREAS WITH COMPLAINTS:
 - SAN DIEGO SCHOOL DISTRICT (DESCRIBED)
 - CALVIN TRANSPORTATION CO., STANISLAPE N.J. -
 75 VEH. IN FLEET, 2 LHM AS A CORRECTION THIS MO
 6.2L DIESEL, G-30s
 VIN # 29BGG35J7F9196006
 # 29BGG35J3F9137517
 (VIN HISTORIES CLEAN)
 DAVE BRUE REED CALL YESTERDAY.
 - (UNKNOWN SOURCE) NORTH DAKOTA
 (1) LH G-30 CRACKED
 OTHER INFO NOT IMMEDIATELY AVAILABLE

000203



1624631-115 2101716



5.2m Dingo S. Adult Dist. #1
 L. 1.5m R. 1.5m
 2.2m S. 1.4m 104101766
 5.2m 1.6m Dist. #14026555?

ILLEGIBLE



0000



2.6.33
 #2 520 25 41
 (Chandrasekhar Ramesh 6792)

060204



October 12, 1987

Saginaw Division
General Motors Corporation
Detroit Gear & Axle
1840 Holbrook
Detroit, MI 48212

Attention: Dave Pokriefka
Chief Inspector

Subject: Lower Control Arm, P/N 15594133

Mr. Pokriefka:

Per our conversation of 10/8/87, I am shipping to you one lower control arm (p/n 15594133) from a P-30 truck which had broken out at the ball stud hole. Information regarding the part is limited, except that it is from a vehicle operated by American Bakeries, (VIN: 1GDHP32J6F3508398; mileage: 56,746).

We would like you to examine the part and issue us a report detailing your findings and addressing possible cause(s) of breakage and parts conformance to specifications. The parts can be scrapped after your investigation is completed. If I can be of any additional assistance, please contact me (8-396-3438).

Thank-you,

Gary L. Haviland
Reliability Metallurgist
Special Analysis Group
8-396-3438
Reliability Laboratories
Truck & Bus Group
GENERAL MOTORS CORPORATION

/ncd

000205

glh10127



From the desk of

P.F. (Paul) Birsa

9-28-89
American Bakeries

1GDHP30IGF3508398

10-1-85 D.D

56,700 mi

PT #

15594133 Lower Control ARM

CRACKS AROUND Ball JOINT

Seat -

BALL JOINT SEPARATED FROM
CONTROL ARM

ILLEGIBLE

on 6/1/89
Tues 7-11-89

Ex: Wm 10-1-85

56,700 mi

15594133

1




000205

LOWER CONTROL ARM CRACKS
1984-87 30 SERIES TRUCKS
ALLEGED PROBLEM

18 FRIDAY, JANUARY 29, 1988 1

FREQUENCY BAR CHART

ALLEG
LEFT CNTRL ARM
UNKNOWN
RIGHT CNTRL ARM




000207

LOWER CONTROL ARM CRACKS
1994-97 50 SERIES TRUCKS
DIVISION

18 FRIDAY, JANUARY 29, 1998 2

FREQUENCY BAR CHART




000208

LOWER CONT. - ARM CRACKS
1984-87 3D SERIES TRUCKS
BSTYLE

18 FRIDAY, JANUARY 29, 1988 3

FREQUENCY BAR CHART




000209

LOWER CONTROL ARM CRACKS
1984-87 SUBARUS TRUCKS
ENGINE

18 FRIDAY, JANUARY 29, 1988

4

FREQUENCY BAR CHART




000210

LOWER CONTROL ARM CATCHES
AND POSSIBLE TRUCKS
1984-87 MODEL YEAR

18 FRIDAY, JANUARY 29, 1988 5

FREQUENCY BAR CHART



000211


LOWER CONTROL ARM CRACKS
1984-1985 SEARS TRUCKS
INCIDENT DATE

11:18 FRIDAY, JANUARY 29, 1988

6

IDATE1

FREQUENCY BAR CHART



0000212

LOWER CONTROL AREA CHUCKS
1984-1985
REPORT DATE

11:48 FRIDAY, JANUARY 29, 1988

7

FREQUENCY BAR CHART

ROUTE	REQ	CUM.	PERCENT	CUM.
	FREQ		PERCENT	PERCENT
MAR86	3	3	6.07	6.07
OCT86	4	7	2.22	8.69
NOV86	1	8	2.22	11.11
JAN87	1	9	2.22	13.33
MAY87	1	10	2.22	15.56
JUN87	3	13	6.07	21.63
JUL87	1	14	2.22	23.85
AUG87	4	18	6.07	29.92
SEP87	4	22	6.07	36.00
OCT87	5	27	11.11	47.11
NOV87	16	43	35.56	82.67
DEC87	4	47	6.07	88.74
JAN88	1	48	2.22	90.96

FREQUENCY

0000213

LOWER CONTROL ARM CRACKS
1984-87 30 SERIES TRUCKS
MILEAGE AT INCIDENT
FREQUENCY BAR CHART

MILES

0,0 1
1,001-5
5,001-10
10,001-15
15,001-20
20,001-25
25,001-30
30,001-35
35,001-40
40,001-45
45,001-50
50,001-55
55,001-60
60,001-65
65,001-70
70,001-75
75,001-80
80,001-85
85,001-90
90,001-95
95,001-100
OVER 100K

5 10 15 20 25 30 35 40 45 50

FREQUENCY

11:18 FRIDAY, JANUARY 20, 1988 8

000214

FREQ.	CUM.	PERCENT	CUM.
FREQ	FREQ	PERCENT	PERCENT
0	0	0.00	0.00
0	0	0.00	0.00
2	2	4.44	4.44
0	2	0.00	4.44
2	4	4.44	8.89
0	4	0.00	8.89
2	6	4.44	13.33
1	7	2.22	15.56
0	8	2.22	17.78
4	12	8.89	26.67
7	19	15.56	42.22
8	27	17.78	60.00
5	32	11.11	71.11
5	37	11.11	82.22
3	40	6.67	88.89
0	40	0.00	88.89
0	40	0.00	88.89
0	40	0.00	88.89
3	43	6.67	95.56
0	43	0.00	95.56
0	43	0.00	95.56
2	45	4.44	100.00

ATTACHMENT '3'

000215

GM-278A

ATTACHMENT 'J'

000216

6



Saginaw

Inter-Organizational

Corrected letter

Date: 11-2-87

Subject: FLEET SERVICE PRODUCT REPORT 0325JRW

From: D.H. Pokriefka

To: R.H. Meinhardt

FINK BAKERY

3/4 Ton Lower Control Arm

#1 Left Hand

CROSS SHAFT BUSHING TORQUE: 300 Ft Lbs
250 Ft Lbs
Spec 125 min.

SHAFT MOVEMENT: Free
JOUNCE BUMPER: Missing

Brackets: Shock Bracket OK
Jounce Bracket repaired hand weld and heavy crash thru witness marks.

BUSHINGS: Seated

BALL STUD: Present "O" pushout load.

TEARDOWN INSPECTION: Arm stamping is cracked from outer wall end face to the ball stud mounting hole. Stamping source is SKD (SEE LAB REPORT #6-39)

3/4 Ton Lower Control Arm

#2 Left Hand

CROSS SHAFT BUSHING TORQUE: 200 Ft Lbs
150 Ft Lbs
Spec 125 min

SHAFT MOVEMENT: Free

JOUNCE BUMPER: Missing

BRACKETS: Shock Bracket OK
Jounce Bracket missing welds did pull metal

BUSHINGS: Seated

BALL STUD: Missing

TEARDOWN INSPECTION: Same as # 1

000212

FLEET SERVICE PRODUCT REPORT 0325JRW
July 9, 1986 continued

3/4 Ton Lower Control Arm
3 Left Hand

CROSS SHAFT BUSHING TORQUE 250 Ft Lbs
 200 Ft Lbs
 Spec 125 min.

SHAFT MOVEMENT: Free

JOUNCE BUMPER: Compressed

BRACKETS: Shock Brkt OK

BUSHING: Seated

BALL STUD: Present "O" pushout load

TEARDOWN INSPECTION: Same as # 1

SUMMARY: The lower control arm stamping from SKD Company appears to have a small radius at the transition of the side wall to the ball stud nose. Current stampings also have a small radius in the same area. SKD has changed the trim to increase the radius to 1 inch and provide additional strength in the ball stud area (See Sample)

in addition the customer may be using the front suspensions at max or beyond max load range which is evidenced by broken welds and compressed jounce bumpers. Suggest a heavier rated front suspension be used (14032908 H-22) that has reinforcements at all critical points.

Correction: Additional inspection and dimensional checks have revealed that the stampings are from SKD. D.H.P. 11-2-87

D. H. Pokriefka

D. H. Pokriefka
Chief Inspector. Plant # 56

000-218



Current Product
Engineering

General Motors Corporation

March 31, 1988

GM-278A

Mr. Michael B. Brownlee
Director
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Mr. Brownlee:

NEF-121rpb
EA88-007

This letter will supplement our January 29, 1988 response to EA88-007 pertaining to cracks in lower control arms of certain Chevrolet and GMC 30 Series trucks.

In our response to EA88-007, we advised you that an investigation to determine actual vehicle loads, use history and modifications, if any, in the field was in progress. This data was needed to further identify the causal and contributory factors which have produced lower control arm cracks and to assess the risk to motor vehicle safety created by those factors. Further, we advised that we would inform the NHTSA as to the results of our investigation upon completion of this effort.

To date our investigation of the field incidents for P-30 vehicles equipped with gasoline or diesel engines and for G-30 vehicles equipped with diesel engines has been completed. The results of this part of our investigation have been referred to the appropriate Product Problem Evaluation Committee (PPEC) for their consideration and recommendation. A PPEC recommendation would then be forwarded to management for their consideration. We will advise you as to the results of this review which we expect to be completed by the end of May.

Concurrently, the investigation of G-30 vehicles equipped with gasoline engines and the investigation of C-30 and R-30 vehicles is still in process. We will further advise NHTSA as to the results of this continuing investigation.

Our investigation to date has not identified any additional accidents or injuries subsequent to those identified in our response to EA88-007.

Sincerely,

Thomas Terry
C. Thomas Terry
Manager
Product Investigations

000219

INFLUENCED RECALL CAMPAIGNS

NAME OF MANUFACTURER: GENERAL MOTORS CORP.

RECALL CAMPAIGN NUMBER: 88V-110

ACTION THAT INFLUENCED RECALL:

PE: _____

EA: 88-067

CASE: _____

CIR: _____

OTHER: _____

000220

RECEIVED

1988 JUL -6 PM 4:18



Current Product
Engineering

General Motors Corporation

July 6, 1988

Mr. Michael B. Brownlee
Director
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
Washington, D.C. 20590

88V-110 (01)

Dear Mr. Brownlee:

The following information is submitted pursuant to the requirements of 49 CFR 573.5 as it applies to a determination by General Motors of a defect related to motor vehicle safety involving certain 1985 and 1986 "G-30" and "P-30" light duty truck models.

573.5(c)(1). GM Truck & Bus and Chevrolet Motor Divisions of General Motors Corporation.

573.5(c)(2)(3)(4). This information is shown on the attached sheet.

573.5(c)(5). General Motors has determined that a defect which relates to motor vehicle safety exists in some 1985-86 P3 and G3 model trucks. The left-hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

573.5(c)(6). The first field report was received by General Motors in March 1986. Control arms used in production were revised in July 1986. An investigation to review the condition of vehicles produced before that date was initiated in October 1987.

573.5(c)(8). This information is set forth in the dealer bulletin.

573.5(c)(9). Representative copies of the owner notification letter and dealer bulletin are attached.

Very truly yours,

C. Thomas Terry
C. Thomas Terry

Manager

Product Investigations

attachment
CAMP.20/cm

000221

573.5(c)(2), (3), (4)

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR
PLUS INCLUSIVE DATES OF MANUFACTURE

MAKE	MODEL SERIES	MODEL YEAR	NUMBER INVOLVED	INCLUSIVE		DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.	EST. NO. W/CONDITION
				MANUFACTURING (FROM)	DATES (TO)		
GMC	P3 G3	1985	2,702	08/84	10/85		
		1985	242	09/84	07/85		
GMC	P3 G3	1986	1,318	10/85	08/86		
		1986	613	08/85	07/86		
		GMC Total	4,875				
Chev.	P3 G3	1985	8,071	08/84	10/85		
		1985	412	08/84	08/85		
Chev.	P3 G3	1986	5,223	10/85	08/86		
		1986	2,904	08/85	07/86		
		Chev. Total	16,610				
GM TOTAL			21,485				

* All affected vehicles
will be corrected

88V-110 (02)

000222

Dear General Motors Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has determined that a defect which relates to motor vehicle safety exists in some 1985-1986 P3 and G3 model trucks. The left hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

To prevent this condition from occurring it will be necessary to repair or replace the lower left control arm on your vehicle. This service will be completed for you at no charge.

Instructions for performing this service have been sent to your GMC truck dealer. Please contact your dealer to arrange a service date. The labor time necessary to perform this correction will be approximately one hour. Please ask your dealer how much additional time will be needed to process your vehicle. Parts will be available approximately _____ 1988.

Your GMC Truck dealer is best equipped to obtain parts and provide service to ensure your vehicle is inspected and/or corrected as promptly as possible. However, if you take your vehicle to your dealer on the agreed service date and they do not service this condition on that date or within five days, we recommend you contact your nearest GMC Truck Zone Office by telephone. The Zone Office will assist you and your dealer in getting your vehicle serviced. The locations and telephone numbers of GMC Truck Zone Offices have been attached for your convenience.

After contacting your dealer and the Zone Office, if you are still not satisfied that we have done our best to remedy this condition without charge within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, D.C. 20590, or call 800-424-9393 (Washington, D.C. residents use 346-0123).

The enclosed owner reply card identifies your vehicle. Presentation of this card to your dealer will assist making the necessary correction to your vehicle in the shortest possible time. If you have sold or traded your vehicle, please let us know by completing the postage paid owner reply card and returning it to us.

We are sorry to cause you this inconvenience, however, we have taken this action in the best interest of your safety and continued satisfaction with our products.

GMC TRUCK DIVISION
GENERAL MOTORS CORPORATION

000223

88V-110 (04)

NUMBER
GROUP 3C Front Suspension
DATE: ____ 1988

SUBJECT: LH Lower Control Arm Cracking

MODELS: 1985-86 P3 Model Trucks with Gas and Diesel Engines
and G3 Vans with 6.2 L Diesel Engines (LL4)

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent vehicle at no charge, or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule appointments with owners and to repair their vehicles as soon as possible. As you will see in reading the attached copy of the letter which is being sent to owners, the owner is being instructed to contact the nearest GMC Zone Office if the dealer does not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed how to contact the National Highway Traffic Safety Administration.

DEFECT INVOLVED

General Motors has determined that a defect which relates to motor vehicle safety exists on some 1985-86 P3 and G3 model trucks. The left-hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

To prevent this condition, GM is recommending that owners of these vehicles be notified and instructed to have the lower control arm inspected and replaced if necessary.

00C22A

88V-110 (05)

VEHICLES INVOLVED

Involved are certain P3 model trucks with gas and diesel engines and G3 vans equipped with 6.2 L Diesel engines (RPO LL4) only built within the following VIN breakpoints:

MODEL YEAR	MODEL	ASSEMBLY PLANT	FROM	THROUGH
1985	P3	Detroit	F3500001	F3510494
	G3	Scarborough	F4500663	F4525796
1986	P3	Detroit	G3500001	G3504509
	G3	Scarborough	G4500456	G4529600

The specific vehicles involved in this campaign have been identified by Vehicle Identification Number Computer Listings. These listings are furnished to all involved dealers with the campaign bulletin.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to perform the required service described under Service Procedure for all vehicles subject to this campaign at no charge to owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

Whenever a vehicle subject to this campaign is taken into your new or used vehicle inventory, or it is in your dealership for service in the future, you should take the steps necessary to ensure the campaign correction has been made before reselling or releasing the vehicle.

Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this bulletin.

If no owner's name and address were available to GMC Truck Division at the time of campaign initiation, the dealer will determine the owner's name and address from the dealership sales records. Please provide this information directly on the second copy of the listing next to the applicable VIN so that our records may be updated and the appropriate notification is led to the owner. This second copy should then be submitted to the address listed below in the previously supplied yellow campaign envelopes.

GMC Truck Division
General Motors Corporation
101 Union Street
Plymouth Michigan 48170

000225

88V-110 (06)

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by GMC Truck Division (see copy of owner letter included with this bulletin). A listing of owner names and addresses has been furnished to the involved dealer to enable dealers to follow up with owners involved in this campaign. This listing may contain owner names and addresses obtained from state motor vehicle registration records. The use of such motor vehicle registration data for any other purpose is a violation of law in several states. Accordingly, you are urged to limit the use of this listing to this campaign.

SERVICE INFORMATION

G3,P3 LOWER CONTROL ARM REPLACEMENT

TOOLS REQUIRED:

- J 23028-02 Spring Remover and Installer
- J 23742 Ball Joint Remover

REMOVAL

1. Remove 2/3 of the brake fluid from the master cylinder.
2. Raise the vehicle and support it with suitable safety stands.
3. Mark the relationship of the wheel to the hub.
4. Remove the wheel and tire assembly.
5. Remove the brake caliper. Position a C-clamp around the outer pad and caliper. Tighten the C-clamp until the piston bottoms in its bore (figure 1). Remove the caliper mounting bolts (figure 2). Lift out the caliper. Suspend the caliper so that the flexible hose is not strained (figure 3).
6. Disconnect the shock absorber at the lower end and move it aside (figure 4).
7. Remove the stabilizer bar retaining nuts, bolts, and clamps at the lower control arm (figure 5).
8. Remove the stabilizer bar from the lower control arm.
9. Remove the grease fittings from the ends of the pivot bar.
10. Secure J 23028-02 to a suitable floor jack.

CAUTION: Failure to secure J 23028-02 to a suitable floor jack could result in personal injury.

000226

11. Place J 23028-02 under the lower control arm shaft (figure 6)
12. Install a chain around the coil spring and through the lower control arm as a safety precaution.
13. Raise the jack to remove the tension from the lower control arm shaft.
14. Remove the U-bolt's retaining nuts and washers.
15. Remove the U-bolts.
16. Lower the control arm by slowly releasing the jack until the spring can be removed.
17. Remove the spring and the safety chain only after all compression force has been removed from the spring.
18. Continue to support the inboard end of the lower control arm with a jack and J 23028-02.
19. Remove the lower ball joint cotter pin. Throw it away.
20. Loosen the lower ball joint retaining nut one turn.
21. Install J 23742, with the large cup end over the upper ball joint retaining nut (figure 7)
22. Extend the threaded end of J 23742 until the lower ball joint stud loosens from the steering knuckle.
23. Remove J 23742.
24. Remove the nut.
25. Remove the lower control arm assembly.
26. Remove the rubber bumper from the lower control arm.
On G van models the bumper is retained by a "tree" The bumper is pried free.
On P models the bumper is retained by a nut. Remove the nut and then remove the bumper.

INSTALLATION

1. Install the lower control arm ball joint stud into the steering knuckle.
2. Install the balljoint retaining nut on the stud. Snug the nut down but do not tighten.

000227

88V-110 (08)

3. Secure J 23028-02 to a suitable floor jack.

CAUTION: Failure to secure J 23028 to a suitable floor jack could result in personal injury.

4. Support the inboard end of the lower control arm with J 23028-02.
5. Install the spring on the lower control arm. Secure the spring to the lower control arm with a chain.
6. Position the spring on its mount.
7. Slowly raise the lower control arm into position.
8. Line up the front indexing hole in the pivot shaft with the crossmember attaching stud (figure 8)
9. Install the U-bolts, washers, and nuts.
10. Tighten the U-bolt nuts to 115 N·m (85 ft·lbs.)
11. Tighten the ball joint nut to 122 N·m (90 ft·lbs.)
12. Install the new cotter pin in the ball joint stud. The nut may be tightened to a maximum of 176 N·m (130 ft·lbs.) in order to align the cotter pin holes.
13. Lower the floor jack and remove J 23028-02.
14. Install the stabilizer bar to the lower control arm.
15. Install the stabilizer bracket, bolts, washers and nuts.
16. Tighten the nuts to 33 N·m (24 ft·lbs.)
17. Install the lower end of the shock absorber to the lower control arm.
18. Install the bolt, washer, and nut.
19. For the G3 vehicle, tighten the nut to 103 N·m (80 ft·lbs.)
For the P3 vehicle, tighten the nut to 80 N·m (59 ft·lbs.)
20. Remove the caliper from its hanger.
21. Install the caliper assembly on the brake.
22. Install the caliper support bolts. Tighten the bolts to 50 N·m (37 ft·lbs.)
23. Install the wheel and tire. Make sure the alignment marks match.

9006228

88V-110 (09)

24. Install the wheel nuts.
25. Tighten the nuts to 160 N·m (120 ft. lbs.)
26. Lower the vehicle.
27. Pump the brake pedal several times to make sure that the brake pedal is firm before moving the vehicle.
28. Check the brake fluid level in the master cylinder and fill to the proper level.

PARTS INFORMATION

Parts are to be obtained from General Motors Service Parts Operation (GMSPD). To ensure that these parts will be obtained as soon as possible, they should be ordered from GMSPD on a C.I.O. order with no special instruction code, but order on an advise code (2).

PART NUMBER	DESCRIPTION	QUANTITY
15594133	LH Lower Control Arm Assembly P3 model with R05 dual rear wheels	1
14026581	LH Lower Control Arm Assembly P3 model without R05 dual rear wheels	1
14026585	LH Lower Control Arm Assembly G3 V6 model	1

WARRANTY INFORMATION

Dealers should submit a warranty claim on each vehicle completed under this campaign.

LABOR OPERATION NUMBER	DESCRIPTION	*TIME ALLOWANCE	TROUBLE CODE
V 4220	Replace Lower Left Control Arm	0.9 Hr	96

*For dealer to receive Advise Time Allowance associated with this campaign, add 0.1 hour to the Labor Operation Time Allowance.

000229

88V-110 (10)

CAMPAIGN IDENTIFICATION LABEL

Each vehicle corrected in accordance with the instructions outlined in this product campaign bulletin will require a Campaign Identification Label. Each label provides a space to include the fifteen digit dealer code of the dealer performing the campaign service. The information should be inserted with a typewriter or ballpoint pen.

Each Campaign Identification Label is to be located on the radiator core support in an area which will be visible when the vehicle is brought in for periodic servicing by the owner.

Apply Campaign Identification Label only on a clean dry surface.

ADMINISTRATIVE PROCEDURE

Procedures covering this campaign are outlined in Section V of your dealership's GMC Truck Classification Processing Manual #P 8719.

GMC Truck bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GMC Truck dealer for information on whether your vehicle may benefit from the information.

6-230

88V-110 (11)




Figure No. 1





Figure No. 2



000231




Figure No. 4




Figure No. 5

88V-110 (13)




Figure No. 6




Figure No. 7




Figure No. 8

JUL 21 1988

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. C. Thomas Terry
Manager, Product Investigations
General Motors Technical Center
30200 Mound Road
Warren, MI 48090-9010

NEF-121rpb
EA88-007

Dear Mr. Terry:

This refers to your defect report of July 6, 1988, concerning left lower control arms cracking on 1985 and 1986 "G-30" and "P-30" light trucks.

For purposes of this information request, definitions of subject vehicles, General Motors (GM), and alleged defect remain the same as stated in our letter of November 19, 1987, concerning this subject.

In order for my staff to complete their evaluation of the alleged defect, additional information is required. Pursuant to Sections 108 and 112 of the National Traffic and Motor Vehicle Safety Act (the Act), please provide numbered responses to the following items. Please repeat each item verbatim before the response. If any information has been provided to this office in response to a previous information request on this matter, that information need not be resubmitted. All other information must be submitted as requested. The submitted information is to include, but not be limited to, all written reports or documents; transcriptions, tapes, or other documentation of oral communications; and information contained on electronic storage media. If you cannot answer any specific question, please state the reason.

- 1 Identify the number of vehicles GM has sold by make, model, and model year, and built with the irregularly formed control arms described in Response 4 of your October 22, 1987 letter to this office (GM278), which concerns the alleged defect.

000234

2. Explain GM's rationale for recalling some, but not all vehicles equipped with the irregularly formed control arms referenced in Question 1.
3. GM's response to Question 21 of the National Highway Traffic Safety Administration (NHTSA) November 19, 1987 Information Request on this subject was incomplete. Therefore, furnish GM's opinion of the alleged defect in the subject vehicles. Please include an assessment of the following:
 - a. the causal or contributory factors which may result in the alleged defect;
 - b. the failure mode;
 - c. the risk to motor vehicle safety created by the alleged defect; and
 - d. any warning of the alleged defect.
4. GM's letter of March 31, 1988, to NHTSA stated the investigation of G-30 vehicles equipped with gasoline engines and the investigation of C-30 and R-30 vehicles is still in process. Identify the current status of this investigation, the results and recommendations, or projected date of completion, if still ongoing.
5. Furnish a copy of all documents not specifically requested which GM believes are relevant or were used in formulating its assessment of the alleged defect.
6. Furnish any new information of which GM is aware concerning any report, document, or information which may have been previously provided by GM. Also, furnish any additional information of which GM is aware concerning the reports provided by NHTSA on this matter.

It is important that GM respond to this letter on time. This letter is being sent pursuant to Section 112 of the Act, which authorizes this agency to conduct any investigation which may be necessary to enforce Title I of the Act. Your failure to respond promptly and fully to this letter may be construed as a violation of Section 108(a)(1)(B) of the Act.

Your written response, in triplicate, referencing the identification codes in the upper right hand corner of page 1 of this letter, must be submitted to this office within 25 working days from your receipt of this letter. If you find that you cannot respond within the allotted time with all the requested information, you must request an extension from the Director, Office of Defects Investigation, no later than 5 working days prior to the due date for your response. A telephone request for an extension may be made to the Director at (202) 366-2850, but it must be confirmed in writing. On-time delivery of partial submissions should be made when circumstances prevent meeting the required delivery schedule.

000235

If any portion of your response is considered confidential information, include all such material in a separate enclosure marked confidential. In addition, you must submit a copy of all such confidential material directly to the Chief Counsel of NHTSA and comply with all other requirements of 49 CFR Part 512, Confidential Business Information.

If you have any technical questions concerning this matter, please contact Mr. Richard Boyd of my staff at (202) 366-5194.

Sincerely,

Original signed by
James P. Talantino

Michael B. Brownlee, Director
Office of Defects Investigation
Enforcement

000236

JUL 22 1988

Mr. Dan Hargraves
Assistant Supervisor Fleet Maintenance
San Diego Unified School District
Fleet Maintenance
1826 Irving Avenue
San Diego, CA 92113


NEF-121rpb
EA88-007

Dear Mr. Hargraves:

This refers to your letter of August 7, 1987, concerning lower control arms cracking on your G-30 school buses. As you are aware, we have been conducting an Engineering Analysis on this matter with General Motors (GM). On July 6, 1988, they notified us that a safety recall would be conducted on 1985 through 1986 P3 model trucks with gas and diesel engines, and G3 vans with 6.2 diesel engines. A copy of GM's correspondence has been included for your information. Although the investigation is still ongoing for other models and engine combinations, it appears that vehicles in your fleet are covered by the safety recall mentioned above.

We wish to thank you for notifying us of this matter and providing the necessary information needed to pursue the investigation. Should you have any questions concerning this issue or any other safety related matter, please contact Mr. Richard Boyd of my staff at (202) 366-5194.

Sincerely,


Michael B. Brownlee, Director
Office of Defects Investigation
Enforcement

Enclosure

000237

RECEIVED

1988 JUL -6 PM 4:18



Current Product
Engineering

General Motors Corporation

July 6, 1988

Mr. Michael B. Brownlee
Director
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
Washington, D.C. 20590

Dear Mr. Brownlee:

The following information is submitted pursuant to the requirements of 49 CFR 573.5 as it applies to a determination by General Motors of a defect related to motor vehicle safety involving certain 1985 and 1986 "G-30" and "P-30" light duty truck models.

573.5(c)(1). GM Truck & Bus and Chevrolet Motor Divisions of General Motors Corporation.

573.5(c)(2)(3)(4). This information is shown on the attached sheet.

573.5(c)(5). General Motors has determined that a defect which relates to motor vehicle safety exists in some 1985-86 P3 and G3 model trucks. The left-hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

573.5(c)(6). The first field report was received by General Motors in March 1986. Control arms used in production were revised in July 1986. An investigation to review the condition of vehicles produced before that date was initiated in October 1987.

573.5(c)(8). This information is set forth in the dealer bulletin.

573.5(c)(9). Representative copies of the owner notification letter and dealer bulletin are attached.

Very truly yours,

C. Thomas Terry
C. Thomas Terry
Manager

Product Investigations

000-238

24

573.5(a)(2),(3),(4)

VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR
PLUS INCLUSIVE DATES OF MANUFACTURE

<u>MAKE</u>	<u>MODEL SERIES</u>	<u>MODEL YEAR</u>	<u>NUMBER INVOLVED</u>	<u>INCLUSIVE MANUFACTURING DATES (FROM) (TO)</u>	<u>DESCRIPTIVE INFO. TO PROPERLY IDENT. VEH.</u>	<u>EST. NO. W/CONDITION</u>
GMC	P3 — G3 —	1985 1985	2,702 242	08/84 09/84	10/85 07/85	Unknown*
GMC	P3 — G3 —	1986 1986	1,318 613	10/85 08/85	08/86 07/86	
		<u>GMC Total</u>	<u>4,875</u>			
Chev.	P3 — G3 —	1985 1985	8,071 412	08/84 08/84	10/85 08/85	
Chev.	P3 — G3 —	1986 1986	5,223 2,904	10/85 08/85	08/86 07/86	
		<u>Chev. Total</u>	<u>16,610</u>			
		<u>GH TOTAL</u>	<u>21,485</u>			

* All affected vehicles
will be corrected

000239

Dear General Motors Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has determined that a defect which relates to motor vehicle safety exists in some 1985-1986 P3 and G3 model trucks. The left hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

To prevent this condition from occurring it will be necessary to repair or replace the lower left control arm on your vehicle. This service will be completed for you at no charge.

Instructions for performing this service have been sent to your GMC truck dealer. Please contact your dealer to arrange a service date. The labor time necessary to perform this correction will be approximately one hour. Please ask your dealer how much additional time will be needed to process your vehicle. Parts will be available approximately _____ 1988.

Your GMC Truck dealer is best equipped to obtain parts and provide service to ensure your vehicle is inspected and/or corrected as promptly as possible. However, if you take your vehicle to your dealer on the agreed service date and they do not service this condition on that date or within five days, we recommend you contact your nearest GMC Truck Zone Office by telephone. The Zone Office will assist you and your dealer in getting your vehicle serviced. The locations and telephone numbers of GMC Truck Zone Offices have been attached for your convenience.

After contacting your dealer and the Zone Office, if you are still not satisfied that we have done our best to remedy this condition without charge within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, D.C. 20590, or call 800-424-9393 (Washington, D.C. residents use 366-0123).

The enclosed owner reply card identifies your vehicle. Presentation of this card to your dealer will assist making the necessary correction to your vehicle in the shortest possible time. If you have sold or traded your vehicle, please let us know by completing the postage paid owner reply card and returning it to us.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

GMC TRUCK DIVISION
GENERAL MOTORS CORPORATION

000-290

NUMBER:
GROUP: 3C Front Suspension
DATE: 1988

SUBJECT: LH Lower Control Arm Cracking

MODELS: 1985-86 P3 Model Trucks with Gas and Diesel Engines
and G3 Vans with 6.2 L Diesel Engines (LL4)

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent vehicle at no charge, or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule appointments with owners and to repair their vehicles as soon as possible. As you will see in reading the attached copy of the letter which is being sent to owners, the owner is being instructed to contact the nearest GMC Zone Office if the dealer does not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed how to contact the National Highway Traffic Safety Administration.

DEFECT INVOLVED

General Motors has determined that a defect which relates to motor vehicle safety exists in some 1985-86 P3 and G3 model trucks. The left-hand lower control arm can crack starting at the rear flange and progress to the ball joint mounting hole and eventually cause the lower ball joint to separate from the control arm. If this happens, a loss of vehicle steering control can occur which could result in a vehicle crash without prior warning.

To prevent this condition from occurring at this time, it will be necessary to install a new left-hand lower control arm on all involved vehicles.

000-241

VEHICLES INVOLVED

Involved are certain P3 model trucks with gas and diesel engines and G3 vans equipped with 6.2 L Diesel engines (RPO LL4) only built within the following VIN breakpoints:

MODEL YEAR	MODEL	ASSEMBLY PLANT	FROM	THROUGH
1985	P3 G3	Detroit Scarborough	F3500001 F4500663	F3510494 F4525796
1986	P3 G3	Detroit Scarborough	G3500001 G4500456	G3504509 G4529600

The specific vehicles involved in this campaign have been identified by Vehicle Identification Number Computer Listings. These listings are furnished to all involved dealers with the campaign bulletin.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to perform the required service described under Service Procedure for all vehicles subject to this campaign at no charge to owners, regardless of mileage, age of vehicle, or ownership, from this time forward.

Whenever a vehicle subject to this campaign is taken into your new or used vehicle inventory, or it is in your dealership for service in the future, you should take the steps necessary to ensure the campaign correction has been made before reselling or releasing the vehicle.

Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this bulletin.

If no owner's name and address were available to GMC Truck Division at the time of campaign initiation, the dealer will determine the owner's name and address from the dealership sales records. Please provide this information directly on the second copy of the listing next to the applicable VIN so that our records may be updated and the appropriate notification mailed to the owner. This second copy should then be submitted to the address listed below in the previously supplied yellow campaign envelopes.

GMC Truck Division
General Motors Corporation
101 Union Street
Plymouth, Michigan 48170

000242

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by GMC Truck Division (see copy of owner letter included with this bulletin). A listing of owner names and addresses has been furnished to the involved dealers to enable dealers to follow up with owners involved in this campaign. This listing may contain owner names and addresses obtained from state motor vehicle registration records. The use of such motor vehicle registration data for any other purpose is a violation of law in several states. Accordingly, you are urged to limit the use of this listing to this campaign.

SERVICE INFORMATION

G3,P3 LOWER CONTROL ARM REPLACEMENT

TOOLS REQUIRED:

- J 23028-02 Spring Remover and Installer
- J 23742 Ball Joint Remover

REMOVAL

1. Remove 2/3 of the brake fluid from the master cylinder.
2. Raise the vehicle and support it with suitable safety stands.
3. Mark the relationship of the wheel to the hub.
4. Remove the wheel and tire assembly.
5. Remove the brake caliper. Position a C-clamp around the outer pad and caliper. Tighten the C-clamp until the piston bottoms in its bore (figure 1). Remove the caliper mounting bolts (figure 2). Lift out the caliper. Suspend the caliper so that the flexible hose is not strained (figure 3).
6. Disconnect the shock absorber at the lower end and move it aside (figure 4).
7. Remove the stabilizer bar retaining nuts, bolts, and clamps at the lower control arm (figure 5).
8. Remove the stabilizer bar from the lower control arm.
9. Remove the grease fittings from the ends of the pivot bar.
10. Secure J 23028-02 to a suitable floor jack.

CAUTION: Failure to secure J 23028-02 to a suitable floor jack could result in personal injury.

000243

11. Place J 23028-02 under the lower control arm shaft (figure 6)
12. Install a chain around the coil spring and through the lower control arm as a safety precaution.
13. Raise the jack to remove the tension from the lower control arm shaft.
14. Remove the U-bolt's retaining nuts and washers.
15. Remove the U-bolts.
16. Lower the control arm by slowly releasing the jack until the spring can be removed.
17. Remove the spring and the safety chain only after all compression force has been removed from the spring.
18. Continue to support the inboard end of the lower control arm with a jack and J 23028-02.
19. Remove the lower ball joint cotter pin. Throw it away.
20. Loosen the lower ball joint retaining nut one turn.
21. Install J 23742, with the large cup end over the upper ball joint retaining nut (figure 7)
22. Extend the threaded end of J 23742 until the lower ball joint stud loosens from the steering knuckle.
23. Remove J 23742.
24. Remove the nut.
25. Remove the lower control arm assembly.
26. Remove the rubber bumper from the lower control arm.
On G van models the bumper is retained by a "tree". The bumper is pried free.
On P models the bumper is retained by a nut. Remove the nut and then remove the bumper.

INSTALLATION

1. Install the lower control arm ball joint stud into the steering knuckle.
2. Install the ball joint retaining nut on the stud. Snug the nut down but do not tighten.

000244

3. Secure J 23028-02 to a suitable floor jack.

CAUTION: Failure to secure J 23028²² to a suitable floor jack could result in personal injury.

4. Support the inboard end of the lower control arm with J 23028-02.
5. Install the spring on the lower control arm. Secure the spring to the lower control arm with a chain.
6. Position the spring on its mount.
7. Slowly raise the lower control arm into position.
8. Line up the front indexing hole in the pivot shaft with the crossmember attaching stud (Figure 8)
9. Install the U-bolts, washers, and nuts.
10. Tighten the U-bolt nuts to 115 N·m (85 ft·lbs.)
11. Tighten the ball joint nut to 122 N·m (90 ft·lbs.)
12. Install the new cotter pin in the ball joint stud. The nut may be tightened to a maximum of 176 N·m (130 ft·lbs.) in order to align the cotter pin holes.
13. Lower the floor jack and remove J 23028-02.
14. Install the stabilizer bar to the lower control arm.
15. Install the stabilizer bracket, bolts, washers and nuts.
16. Tighten the nuts to 33 N·m (24 ft·lbs.)
17. Install the lower end of the shock absorber to the lower control arm.
18. Install the bolt, washer, and nut.
19. For the G3 vehicle, tighten the nut to 103 N·m (80 ft·lbs.)
For the P3 vehicle, tighten the nut to 80 N·m (59 ft·lbs.)
20. Remove the caliper from its hanger.
21. Install the caliper assembly on the brake.
22. Install the caliper support bolts. Tighten the bolts to 50 N·m (37 ft·lbs.)
23. Install the wheel and tire. Make sure the alignment marks match.

000245

24. Install the wheel nuts.
25. Tighten the nuts to 160 N·m (120 ft. lbs.)
26. Lower the vehicle.
27. Pump the brake pedal several times to make sure that the brake pedal is firm before moving the vehicle.
28. Check the brake fluid level in the master cylinder and fill to the proper level.

PARTS INFORMATION

Parts are to be obtained from General Motors Service Parts Operation (GMSPD). To ensure that these parts will be obtained as soon as possible, they should be ordered from GMSPD on a C.I.D. order with no special instruction code, but order on an advise code (2)

PART NUMBER	DESCRIPTION	QUANTITY
15594133	LH Lower Control Arm Assembly P3 model with R05 dual rear wheels	1
14026581	LH Lower Control Arm Assembly P3 model without R05 dual rear wheels	1
14026585	LH Lower Control Arm Assembly G3 Van model	1

WARRANTY INFORMATION

Dealers should submit a warranty claim on each vehicle completed under this campaign.

LABOR OPERATION NUMBER	DESCRIPTION	*TIME ALLOWANCE	TROUBLE CODE
V 4220	Replace Lower Left Control Arm	0.7 Hr.	96

*For dealer to receive Administrative Time Allowance associated with this campaign, add 0.1 hour to the Labor Operation Time Allowance.

DOC-246

CAMPAIGN IDENTIFICATION LABEL

Each vehicle corrected in accordance with the instructions outlined in this product campaign bulletin will require a 'Campaign Identification Label'. Each label provides a space to include the five (5) digit dealer code of the dealer performing the campaign service. This information may be inserted with a typewriter or ball point pen.

Each 'Campaign Identification Label' is to be located on the radiator core support in an area which will be visible when the vehicle is brought in for periodic servicing by the owner.

Apply 'Campaign Identification Label' only on a clean dry surface.

ADMINISTRATIVE PROCEDURE

Procedures covering this campaign are outlined in Section V of your dealership's 'GMC Truck Claims Processing Manual' #P 8719.

GMC Truck bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GMC Truck dealer for information on whether your vehicle may benefit from the information.

2000-247




Figure No. 1





Figure No. 2



GOC-248





Figure No. 4

38. Nut
39. Washer
40. Bushing
41. Washer
42. Clamp
43. Bolt
52. Clamp
53. Bushing
54. Bolt
55. Washer
57. Washer
58. Nut
59. Stabilizer Bar



906249




Figure No. 6




Figure No. 7




Figure No. 8

000-250